


Questions? Call 1-800-810-1053



a **xylem** brand

REPAIR PARTS / RHSC R2





Order Online: www.PumpCatalog.com

Item	Part No.	Part Name	Quantity	Pattern No.
3	①1K291	Casing	1	59039
8	1K204	Intermediate stage	(1 - 2 stage)	59157
			(2 - 3 stage)	
15	1K206	Motor adapter	1	59156
	2K322	Impeller - ¾ HP	2	
5	2K289	Impeller - 1 HP	2	
5	2K323	Impeller - 1½ HP	2	
	2K289	Impeller - 2 HP	3	
18	4K376	Foot (old style)	1	
18A	15K60	Base and rubber channel	1	
21	4K327	Wear ring	(1 per 1K291 and 1K204)	
7	4K328	Sleeve (1 - 2 stage)		
			(2 - 3 stage)	
6	4K396	Coverplate	(1 per impeller)	
12	4K379	Seal retainer	1	
	@4K331	Shaft extension assembly -	1	
9, 10,		2 stage, ¾, 1 and 1½ HP		
11, 12	@4K332	Shaft extension assembly - 3 stage, 2 HP	1	
22	5K7	Deflector	1	
17	5K147	O-ring - motor adapter bolts	4	
4	5K178	O-ring - casing and intermediate stage	1 per stage	
1	6K2	Pipe plug ¼" NPT	3	
13, 14	10K10	Shaft seal assembly	1	
9	13K43	Impeller bolt	1	
19	13K71	Bolt - foot to adapter	1	
16	13K81	Bolt - adapter to motor	4	
10	13K212	Washer - impeller (1) and adapter (4)	5	
2	13K213	Bolt - casing to adapter, 2 stage	4	
2	13K214	Bolt - casing to adapter, 3 stage	4	

Motor Codes						
Item	HP	Model	Order No.			
	3/4	HSC07	J05853L			
20	1	HSC10	J06853L			
20	11/2	HSC15	J07858L			
	2	HSC20	J08854L			

NOTES:

- ① 1K291 casing replaced the 1K201 which was on both the HSJ and the original HSC.
- ② Shaft Extension Assemblies 4K331 and 4K332 include: shaft extension, 4K379 seal retainer, 13K43 impeller bolt and 13K212 washer.

Xylem Inc.

Phone: (866) 673-0428 www.xylem.com/goulds

